


INSTALLATION INSTRUCTIONS



INSTALLATION INSTRUCTIONS-IL CONNECTOR

TAKE THIS ADJUSTABLE CONNECTOR TO CONNECT TWO TRACK SECTIONS INTO FOLLOWING TURNS: 1) LEFT L TURN. 2) RIGHT L TURN. 3) STRAIGHT I TURN.

CAUTION- Turn off switch at main power source before installing any track or fitting.

- Loosen set screw and insert connector with Embossed Polarity Arrow (Polarity side of two fingers-Grounding contacts) pointing to Debossed Track Polarity line for proper installation (LEFT "L" TURN).
- NOTE: If the connector can not be installed properly and easily, do not force. Remove "L" cover from fitting. Adjust the direction of fitting to be a "I" (STRAIGHT I TURN) or an opposite "L" (RIGHT "L" TURN) and try to connect two tracks by step (1) until it can be connected for proper installation.
- Tighten set screw to lock to track. NOTE: Track ends must be terminated with either a dead end or a connector. Replace cover on fitting and tighten cover screw.

SAVE THIS INSTRUCTIONS

Warning: To avoid the potential risk of fire and shorting, under any circumstances **should not** you use the connectors and end cap **without** busbar stoppers (Drawings below with "X" mark) for your track system.

