


95 Cantiague Rock Road, Westbury NY 11590 ph:516.931.9090 fax:516.931.1254 info@crystorama.com www.crystorama.com

MODEL#:1575-CH-S ASSEMBLY AND DRESSING INSTRUCTIONS

IMPORTANT

TURN OFF THE POWER AT THE MAIN FUSE OR CIRCUIT BREAKER BOX BEF ORE STARTING INSTALL ATION



(SS10mmx6pcs+GS10mmx10pcs+14mmx6pcs+20mmx5pcs)x5pcs

(SS10mmx6pcs+GS10x5pcs+14mmx8pcs+20mmx3pcs)x5Pcs

C= → (SS10mm+SS25mm+76mm)x5Pcs