


## assembly instructions


Family: Flat Iron | Item No. 4034 CH



## **Drawing 1 - Fixture Assembly**



## **Drawing 2 - Glass Installation**



## Vstart here

- 1. Find a clear area in which you can work.
  - 2. Unpack fixture and glass from carton.
  - 3. Carefully review instructions prior to assembly.

\*\*\* The construction of this fixture will be accomplished by first assembling the the main body of the fixture, making all necessary electrical connections, hanging the fixture from the ceiling, and then installing the glass.

**SAFETY WARNING: READ WIRING AND GROUNDING INSTRUCTIONS (I.S. 18)** AND ANY ADDITIONAL DIRECTIONS. TURN POWER SUPPLY OFF DURING INSTALLATION. IF NEW WIRING IS REQUIRED, CONSULT A QUALIFIED **ELECTRICIAN OR LOCAL AUTHORITIES FOR CODE REQUIREMENTS.** 

- 1. Adjust Arms (C) on main body assembly (A) so that they are 180 degrees apart see Drawing 1.
- 2. Thread bottom ball (E) into coupler (H).
- 3. Please refer to the hanging instruction sheet (I.S. 19) provided to continue installation
- 1. Remove threaded socket ring (G) from socket (D) see Drawing 2.
- 2. Slip glass (F) over socket (D) and hold in position.
- 3. Thread socket ring (G) back onto socket (D) and tighten to secure glass (F).
- 4. Fixture can now be lamped accordingly.

Note: Maximum wattage for 4034 fixture is 100 watts per bulb.

2.7.08