
## ASSEMBLING &INSTALLATION INSTRUCTIONS FOR PRODUCT# 7661 7861 For Ceiling Mount Fixtures


## WARNING! SHUT POWER OFF AT FUSE OR CIRCUIT BREAKER.

## MOUNTING THE FIXTURE

- 1. Shut off the power at the fuse box or circuit breaker box. Remove the old fixture from ceiling, including the single bar.
- 2. Carefully unpack your new fixture and lay out all the parts on a clear area. Take care not to lose any small parts necessary for installation.
- 3. Thread the two mounting screws about 1/4"into the pre-drilled holes in the single bar spaced the same distance apart as the holes in the pan (A).
- 4. Attach the single bar to the Junction Box using the two screws from the Junction Box. The side of the single bar marked "GND" must face out.
- 5. Hold the pan (A) towards the single bar and connect the electrical wires as follows (See Fig.2). Connect the black wire from the fixture to the black house (hot) wire; connect the white wire from the fixture to the white house (neutral) wire. Make sure all wire nuts are secured. You may wrap the connections with electrical tape. If your Junction box has a ground wire (green or bare copper) connects fixture's ground wire to it. Other wise attach the bare copper fixture wire to the green ground screw on the single bar. Tuck the wire connections neatly into the ceiling junction box as you are holding the fixture assembly toward the ceiling.
- 6. Finish mounting the pan (A) by placing it over both mounting screws so that the screws protrude from the keyholes in the bottom of the pan (A). Rotate the pan (A) until the screw are seat in the slots of the keyholes and tighten it with a screwdriver.
- 7. Install the light bulbs in accordance with the fixture's specifications. DO NOT EXCEED THE MAXIMUM WATTAGE RATING!
- 8. Attach the glass shade(B) into the glass frame(C), raise the assembly to the pan, aligning the top screw of frame with pan's hole, then tighten it with the finial(D).

Your installation is now complete. Return power to the junction box and test the fixture.





MIN 90°C SUPPLY CONDUCTORS

